

02/22/2006

1087494 - R8 SDMS

Joyce  
Ackerman/EPR/R8/USEPA/US

To David.Wilson@Pacifcorp.com  
cc

02/22/2006 11:49 AM

bcc Joyce Ackerman/EPR/R8/USEPA/US  
Subject Utah Transit Authority property

Hi David - Here is the pdf showing the property UTA purchased from Pacifcorp.

In the CDM report, it shows that the sample for this area was SLR2-00497. I have attached the field notes from that sample. The notes say that the area was excavated to approximately 3 feet and that visible vermiculite was still present.

I would like to talk to you further to see if there's any other information that would be useful to UTA. I will be in the office all day today and tomorrow.

Thanks for your help!



SampleSLR2-00497.pdf

Joyce Ackerman  
On-Scene Coordinator  
Region 8  
303-312-6822

----- Forwarded by Joyce Ackerman/EPR/R8/USEPA/US on 02/22/2006 11:45 AM -----



"DeLoretto, Mary  
(Environmental Studies  
Manager)"  
<MDeLORETTO@uta.cog.ut  
.us>

To Joyce Ackerman/EPR/R8/USEPA/US@EPA  
cc  
Subject PacifiCorp Power Substation site - SLC, Utah

02/21/2006 04:03 PM

Joyce,

Attached is a pdf showing the property UTA purchased from PacifiCorp for the power substation for our Light Rail line. We are expanding our Light Rail system downtown and need to add new facilities at this location and new underground utilities. We do not plan on excavating any deeper than 4 feet.

Can you tell me the aerial extent and depth of the cleanup and whether it included the UTA-owned parcel?

Thanks for your help.

Mary

Mary DeLoretto, P.E.  
Environmental Studies Manager  
Utah Transit Authority

3600 South 700 West  
Salt Lake City, UT 84119  
801-287-2558 (office)  
801-915-5438 (mobile)



SLC substation location.pdf

An aerial photograph of a city street intersection. The street running vertically is labeled '400 West' and the street running horizontally is labeled '100 South'. Two properties are identified with arrows: 'UTA Property' and 'Pacifi. Corp property'. The image is a black and white aerial view with handwritten labels in black ink. The 'UTA Property' label has an arrow pointing to a building on the east side of 400 West, just south of the intersection. The 'Pacifi. Corp property' label has an arrow pointing to a large, rectangular lot on the east side of 400 West, south of the UTA property. The street names are written vertically along the respective streets. The overall image has a grainy, high-contrast appearance typical of older aerial photography.

[illegible]

# LIBBY SISTER SITES FIELD SAMPLE DATA SHEET SOIL-LIKE MATERIALS

Scenario No.: NA Field Logbook No: SLR-04 Page No: 74 Sampling Date: 10/11/04

Address: 1475 400 W. Owner: PACIFICORP

Land Use: (circle) Residential School Commercial Mining Roadway Other ( )

Sampling Team: (circle) CDM PES Other Names: ANDY GORDON

Data Item	Sample 1	Sample 2	Sample 3
Index ID	<b>SLR2- 00497</b>		
Location ID	<u>AG 10/11/04</u>		
Sample Group			
Location Description (circle)	<u>Yard Soil</u> Garden Soil Play Area Driveway Other	Yard Soil Garden Soil Play Area Driveway Other	Yard Soil Garden Soil Play Area Driveway Other
Category (circle)	<u>ES</u> FD	FS FD	FS FD
Matrix Type (circle)	Mining Waste Subsurface Soil <u>Surface Soil</u> Fill Other	Mining Waste Subsurface Soil Surface Soil Fill Other	Mining Waste Subsurface Soil Surface Soil Fill Other
Type (circle)	Grab <u>Comp. # subsamples 5</u>	Grab Comp. # subsamples	Grab Comp. # subsamples
Sample Time	<u>1530</u>		
Top Depth (in.)	<u>0</u>		
Bottom Depth (in.)	<u>2</u>		
Map Location	<u>SEE LOGBOOK #SLR-04</u> <u>Pg. 74</u>		
Field Comments	<u>Sample collected</u> <u>after approx. 3'</u> <u>excavated. Visible</u> <u>vermiculite still present.</u>		
	Entered Validated	Entered Validated	Entered Validated